## brawing no. 502500

Replacement spring (left side) for model 940 doors shipped from 1981 to June 1990. (door has no bearing where axle meets door bracket)

Left/Right side is as observed when standing inside the storage unit looking out at the door. In standard Trac-Rite applications, the latch side is the left side.



## For 940 doors shipped from 1981 to June 1990:

Width range: 9'1" to 10'10" Height range: 2'10" to 10'4"

	Original Spring	<b>Replacement Spring</b>
Wire Diameter	.25"	.25"
Inside Diameter	3.25"	3.25"
Nominal Length	11.75"	11.75"
No. of Coils	47	47
Inch Number Per Turn (IPPT)	70	70

Corresponding right side spring is 502499

